

EPA Notification of Hazardous Waste Site #160739

Environmental Protection Agency
Washington DC 20460

This initial notification information is required by Section 103(c) of the Comprehensive Environmental Response, Compensation, and Liability Act of 1980 and must be mailed by June 9, 1981.

Please type or print in ink. If you need additional space, use separate sheets of paper. Indicate the letter of the item which applies.

REF 61

810608

IL#391

ILS-000-001-279

A Person Required to Notify:

Enter the name and address of the person or organization required to notify.

Name Monsanto Co. - J. F. Queeny Plant
Street 1700 South Second Street
City St. Louis State Missouri Zip Code 63177

B Site Location:

Enter the common name (if known) and actual location of the site.

Name of Site Sauget (Monsanto), Illinois Landfill
Street Falling Springs Road
City Sauget County St. Clair State Illinois Zip Code 62201

C Person to Contact:

Enter the name, title (if applicable), and business telephone number of the person to contact regarding information submitted on this form.

Name (Last, First and Title) McCombs, Max W. - Env. Prot. Supv.
Phone (314) 622-1400

D Dates of Waste Handling:

Enter the years that you estimate waste treatment, storage, or disposal began and ended at the site.

From (Year) Unknown To (Year) 1957

E Waste Type: Choose the option you prefer to complete

Option 1: Select general waste types and source categories. If you do not know the general waste types or sources, you are encouraged to describe the site in Item I—Description of Site.

General Type of Waste:

Place an X in the appropriate boxes. The categories listed overlap. Check each applicable category.

1. ☒ Organics
2. ☒ Inorganics
3. ☒ Solvents
4. ☐ Pesticides
5. ☐ Heavy metals
6. ☐ Acids
7. ☐ Bases
8. ☐ PCBs
9. ☐ Mixed Municipal Waste
10. ☐ Unknown
11. ☐ Other (Specify)

Source of Waste:

Place an X in the appropriate boxes.

1. ☐ Mining
2. ☐ Construction
3. ☐ Textiles
4. ☐ Fertilizer
5. ☐ Paper/Printing
6. ☐ Leather Tanning
7. ☐ Iron/Steel Foundry
8. ☒ Chemical, General
9. ☐ Plating/Polishing
10. ☐ Military/Ammunition
11. ☐ Electrical Conductors
12. ☐ Transformers
13. ☐ Utility Companies
14. ☐ Sanitary/Refuse
15. ☐ Photofinish
16. ☐ Lab/Hospital
17. ☐ Unknown
18. ☐ Other (Specify)

Option 2: This option is available to persons familiar with Resource Conservation and Recovery Act (RCRA) Section regulations (40 CFR Part 261).

Specific Type of Waste:

EPA has assigned a four-digit number to each hazardous listed in the regulations under Section 3001 of RCRA. Enter appropriate four-digit number in the boxes provided. A complete list of hazardous wastes and codes can be obtained by contacting the EPA Region serving the State in which the waste is located.

000119 JUN -881

JUN 08 1981

Region VII R.C. MO

F Waste Quantity:
Place an X in the appropriate boxes to indicate the facility types found at the site.
In the "total facility waste amount" space give the estimated combined quantity (volume) of hazardous wastes at the site using cubic feet or gallons.
In the "total facility area" space, give the estimated area size which the facilities occupy using square feet or acres.

Facility Type

1. ☐ Piles
2. ☐ Land Treatment
3. ☒ Landfill
4. ☐ Tanks
5. ☐ Impoundment
6. ☐ Underground Injection
7. ☐ Drums, Above Ground
8. ☒ Drums, Below Ground
9. ☐ Other (Specify) _____

Total Facility Waste Amount
cubic feet 356,000 **C**
gallons _____
Total Facility Area
square feet _____
acres Unknown

G Known, Suspected or Likely Releases to the Environment:
Place an X in the appropriate boxes to indicate any known, suspected, or likely releases of wastes to the environment.

☐ Known ☐ Suspected ☐ Likely ☐ None
(☒ Do not know)

Note: Items H and I are optional. Completing these items will assist EPA and State and local governments in locating and assessing hazardous waste sites. Although completing the items is not required, you are encouraged to do so.

H Sketch Map of Site Location: (Optional)

Sketch a map showing streets, highways, routes or other prominent landmarks near the site. Place an X on the map to indicate the site location. Draw an arrow showing the direction north. You may substitute a publishing map showing the site location.

I Description of Site: (Optional)

Describe the history and present conditions of the site. Give directions to the site and describe any nearby wells, springs, lakes, or housing. Include such information as how waste was disposed and where the waste came from. Provide any other information or comments which may help describe the site conditions.

J Signature and Title:

The person or authorized representative (such as plant managers, superintendents, trustees or attorneys) of persons required to notify must sign the form and provide a mailing address (if different than address in item A). For other persons providing notification, the signature is optional. Check the boxes which best describe the relationship to the site of the person required to notify. If you are not required to notify check "Other".

Name George F. Knollmeyer, Plant Manager
Street _____
City _____ State _____ Zip Code _____
Signature _____ Date 5/18/81

JO3
☐ Owner, Present
☐ Owner, Past
☒ Transporter
☐ Operator, Present
☐ Operator, Past
☐ Other

**DO NOT
REMOVE
THIS
PAGE!**

RECEIVED BY DYNCORP
March 29, 1995
0511766 RF00041